














Part No.	Drawing	QTY
A		1
B		1
C		1
D		2
E		1
1		6+1
2		2
3		14+1

*Remark: +1 = Spare part


Assembly instructions




B  1PCS	C  1PCS	1  6PCS
--------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------






A





1PCS



<p>D  2PCS</p>	<p>3  4PCS</p>	
---------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------	--








2



2PCS









3






2PCS



3



4PCS




3



4PCS

E



1PCS